Delta Environmental Consultants, Inc.		BORING	WELL LOCATION SKETCH MAP
Page 1 of 1 BORING/WELL NO. B-14 SOIL	BORING LOG		
PROJECT NO./NAME GOB7M-RP50-B.01A201/ARCO Facility No. 6131	LOCATION 3201 Harbor Boulevard		
DRILLING CONTRACTOR/DRILLER Cascade Drilling, Inc./Darren	Costa Mesa, California		•
GEOLOGIST/OFFICE .	APPROVED BY		•
Susan Nielsen/Orange County	Dean A. Richesin, P.G. No.	3587	
DRILLING EQUIPMENT/METHOD	SIZE/TYPE OF BIT	SAMPLING METHOD	START/FINISH DATE
Geoprobe/Direct Push	1.5"/Soil	Direct Push	9/6/05-9/6/05
		•	TOTAL DEPTH
<i>:</i>			35.0

		LITHOLOGY		SAMPLING DATA		
Depth, feet	Graphic Log	Visual Description		Sample No. and Interval	Penetration Rate (Blows/ft.)	PID Vatue (ppm)
		ASPHALT				

		·				

 5_						
		CLAY (CL): brown, medium dense, low plasticity, little fine sand, moist	_5_	8-14-5	883	0
•••						
			••••			
			• • • • • •			
10_		Little fine sand, micaceous	10	B-14-10		0
• • • •					П	Ū
•••						
15			15			
		SAND (SP): yellowish orange/tan, fine to medium grained, micaceous, loose, slightly moist		B-14-15	H	0
			,,,,,			
•••						
20			20			
		Slightly micaceous		B-14-20	***	0
•••						
•••						
*,						
25		Trace silt	<u>25</u>	B-14-25		0
•••						_
		•				
• • • •						
30	minim	. \Medium dense	30		***	
		CLAY (CL): greenish grey, low plasticly, medium stiff, trace very fine micaceous	. <i></i> 	B-14-30		>3,00
<i>_</i>	<i>\$/////</i>	sand, moist				
GROUN WATE	R ///////					
ENCOUNT SEP 6, 2	ERED	SANDY SILT (ML): yellowish brown, very fine grained sand, medium dense, micaceous, wet				
<u>35</u>		inimassoud, was	35			
	***************************************	Boring terminated at 35 feet below ground surface (ft bgs). Groundwater was encountered at 32 ft bgs during drilling. Boring was backfilled with bentonite grounds.		B-14-35	1000	0